Improvements to drain at Vijayalakshmi layout at Bagalagunte in ward no. 14.



Index

- work spot of drain
- work spot of Road
- sketch is not to scale

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Scanned by CamScanner

Audited and admitted for Rs. 5,10,428-00

Passed by Cheque for Rs. 4842580 -00

(.....)

Serial No. 167848 -00

Name of work .....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

Exe. Engineer

BBMP Dasarahalli Division

M A. R. 57 (Rule 116) **No. D**

Measurement Book

60752

N

From ..... To .....

Date	Full description, etc, of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
	56 mtr		80 m				
	46					44 m²	
	30 cm						
	Vijayalakshmi layout main road						
	23 m			100 m²		22 m²	

Index

→ work spot (done)

→ work spot (Cc done)

→ Not to Scale

S.A.O

5/4/2018

Ramachandra

Ele. Engg

5/4/18

ಪಾಲಿಕೆ ಎಂಜಿನಿಯರ್

ದಾಸರಹಳ್ಳಿ ವಿಭಾಗ

ಬೆಂಗಳೂರು

Scanned by CamScanner